

Date: Dec 24, 2021

PCN No#: 122421-1

PCN Title: MCC will update the products packing method for SOT-223 & SOT-89 packages.

Dear Customer:

This is an announcement of change(s) to products that are currently being offered by Micro

Commercial Components Corp(MCC) . We request that you acknowledge receipt of this

notification within 30 days of the date of this PCN. Please refer to the implementation date

of this change as it is stated in the attached PCN form. Please contact your local sales

representative to acknowledge receipt of this PCN.

If you have any questions about PCN's products, please contact your local sales

representative.

Sincerely,

MCC PCN Team



PRODUCT CHANGE NOTICE

| Notification Date | Implementation Date | Change Type | Classification | PCN No | | |
|--|---|---|------------------------|-----------|--|--|
| Dec 24, 2021 | ASAP | Packing Update | Minor | 122421-1 | | |
| | | TITLE | | | | |
| MCC will update the p | oducts packing method for S | OT-223 & SOT-89 packages. | | | | |
| | D | ESCRIPTION OF CHANGE | | | | |
| In order to facilitate propackages. | oduction line operation and q | uality control, MCC will use MBB baç | for products of SOT-89 | & SOT-223 | | |
| | | IMPACT | | | | |
| No change in datashe Table A: Reel Compar | et of electrical parameters . ison. | | | | | |
| | | PRODUCTS AFFECTED | | | | |
| Table B: Affected Part | s List | | | | | |
| | | WEB LINKS | | | | |
| Terms And Condition | s And Conditions: https://www.mccsemi.com/Home/TermsAndConditions | | | | | |
| For More Information | Contact: https://ww | : https://www.mccsemi.com/Contact/Index | | | | |
| | https://www | https://www.mccsemi.com/ProductCategories | | | | |
| Products: | nups.//ww | Williago Chinicollini Toddo Codlogo Choo | | | | |



PRODUCT CHANGE NOTICE

| Table A - Reel Comparison | | | | | |
|---------------------------|--|--------------|--|--|--|
| Item | Before Change | After Change | | | |
| 7 inch Reel | THE CONTROL OF THE CO | M SEE TO | | | |
| 13 inch Reel | TOTAL | | | | |

| Table B - Affected Parts List | | | | | |
|-------------------------------|---------------|-------------|-----------------|--|--|
| BCP51-16-TP | 2SA1213-Y-TP | BCX53-TP | CXT5551-TP | | |
| BCP52-16-TP | 2SB1188-Q-TP | BCX53-16-TP | PXT2222A-TP | | |
| BCP53-16-TP | 2SB1386-R-TP | BCX54-TP | PXT3904-TP | | |
| BCP54-16-TP | 2SC2383P-O-TP | BCX54-16-TP | PXT3906-TP | | |
| BCP55-16-TP | 2SC2383P-Y-TP | BCX55-TP | PXT8050-D-TP | | |
| BCP56-16-TP | 2SC2873-Y-TP | BCX55-16-TP | MC78L05FA-TP | | |
| BCP68-25-TP | 2SC2881-Y-TP | BCX56-TP | MCA1117C-1.8-TP | | |
| PZT2222A-TP | 2SD1664-R-TP | BCX56-16-TP | MCA1117C-2.5-TP | | |
| PZT2907A-TP | 2SD1898-R-TP | BD772-Y-TP | MCA1117C-3.3-TP | | |
| PZT3904-TP | BC869-TP | BD882-Y-TP | MCA1117C-5.0-TP | | |
| PZT5551-TP | BCX52-TP | BSR33-TP | MCA1117C-ADJ-TP | | |
| PZTA42-TP | BCX52-16-TP | CXT5401-TP | | | |