



130 W Cochran St, Unit B  
Simi Valley, CA 93065  
Tel:818-701-4933

---

## Engineering Change Notification

### Feb-11th-2010

Subject : MCC Engineering Change Notification#021110

Title: Bridge Rectifiers Min/Mult Quantity Update

Effective date: Mar-1<sup>st</sup>-2010

Reliability Data: N/A

Samples contact: [Sales@mccsemi.com](mailto:Sales@mccsemi.com)

For question concerning this notification: [techsupport@mccsemi.com](mailto:techsupport@mccsemi.com)

Description and purpose :

This ECN#021110, announcing MCC has determined to update the min/mult quantity for some bridge rectifiers.

Detailed difference as below:

Affected Pn#	Before Change(Min/Mult)	After Change(Min/Mult)
RB151-BP~RB157-BP	1Kpcs	10Kpcs
W005M-BP~W10M-BP	1Kpcs	10Kpcs
2KBP01-BP~2KBP10-BP	1Kpcs	4Kpcs
KBP201-BP~KBP210-BP	1Kpcs	4Kpcs
KBP2005G-BP~KBP210G-BP	1.25Kpcs	5Kpcs
KBP3005G-BP~KBP310G-BP	1.25Kpcs	5Kpcs
RS401GL-BP~RS407GL-BP	1Kpcs	2Kpcs



130 W Cochran St, Unit B  
 Simi Valley, CA 93065  
 Tel:818-701-4933

(cont')

Affected Pn#	Before Change(Min/Mult)	After Change(Min/Mult)
GBU4A-BP~GBU4M-BP	1Kpcs	2Kpcs
GBU6A-BP~GBU6M-BP	1Kpcs	2Kpcs
GBU8A-BP~GBU8M-BP	1Kpcs	2Kpcs
GBU10A-BP~GBU10M-BP	1Kpcs	2Kpcs
GBU15A-BP~GBU15M-BP	1Kpcs	2Kpcs
GBJ6005-BP~GBJ610-BP	0.75Kpcs	1.5Kpcs
GBJ8005-BP~GBJ810-BP	0.75Kpcs	1.5Kpcs
GBJ10005-BP~GBJ1010-BP	0.75Kpcs	1.5Kpcs
GBJ15005-BP~GBJ1510-BP	0.75Kpcs	1.5Kpcs
GBJ20005-BP~GBJ2010-BP	0.75Kpcs	1.5Kpcs
GBJ25005-BP~GBJ2510-BP	0.75Kpcs	1.5Kpcs
GBJ35005-BP~GBJ3510-BP	0.75Kpcs	1.5Kpcs
PB305-BP~PB310-BP	0.2Kpcs	1.6Kpcs
PB605-BP~PB610-BP	0.2Kpcs	1.6Kpcs
MP1005-BP~MP1010-BP	0.2Kpcs	1.6Kpcs
MB805-BP~MB810-BP	0.2Kpcs	1.6Kpcs
MB1005-BP~MB1010-BP	0.2Kpcs	1.6Kpcs
MB1505(W)-BP~MB1510(W)-BP	0.05Kpcs	0.4Kpcs
MB2505(W)-BP~MB2510(W)-BP	0.05Kpcs	0.4Kpcs
MB3505(W)-BP~MB3510(W)-BP	0.05Kpcs	0.4Kpcs
MB5005(W)-BP~MB5010(W)-BP	0.05Kpcs	0.4Kpcs
MP1505(W)-BP~MP1510(W)-BP	0.05Kpcs	0.4Kpcs
MP2505(W)-BP~MP2510(W)-BP	0.05Kpcs	0.4Kpcs
MP3505(W)-BP~MP3510(W)-BP	0.05Kpcs	0.4Kpcs
MP5005(W)-BP~MP5010(W)-BP	0.05Kpcs	0.4Kpcs